

**From:** [Gary Moore](#)  
**To:** [Moore, Gary](#)  
**Subject:** Fwd: FJ Doyle Residential Restoration  
**Date:** Saturday, January 05, 2019 1:56:25 PM

---

----- Forwarded message -----

**From:** **Gary Moore** <[garywmoore1964@gmail.com](mailto:garywmoore1964@gmail.com)>  
**Date:** Sat, Jan 5, 2019 at 9:16 AM  
**Subject:** FJ Doyle Residential Restoration  
**To:** Paige Delgado <[paigedelgadorocks@gmail.com](mailto:paigedelgadorocks@gmail.com)>, John Martin <[Martin.John@epa.gov](mailto:Martin.John@epa.gov)>, Don Edgington <[d.edgington@erllc.com](mailto:d.edgington@erllc.com)>, Alejandro Lara <[alex.lara@westonsolutions.com](mailto:alex.lara@westonsolutions.com)>

All

When I was on-site on 12/28, I noticed that soil was no where near the height of the driveway. My expectation is that soil be even with the height of the driveway and very slowly tapered to a sloped (mowable) ditch.

The backyards of the rental properties shoul slope to the fence with mowable slight swale to the north or south depending on which property.

Not sure how to drain (b) (6) property except away from house.

Gary  
 Sent from my iPhone